



Omítkovací spojky



Těsnění Perbunan
55° Shore A



Páčka se zajišťovacím kroužkem

Vhodné náhradní díly
(Balení : 10 ks)

Øa	Øi	h	Obj.č.	Obj.č.
36	24.5	6	MDR 25	MNH-628
43.5	28.5	6	MDR-X25	MNH-630
53.5	36.5	6	MDR 35	MNH-628
53.5	36.5	6	MDR 35	MNH-628
55	41	6.5	MDR 42	MNH-628
67	51	6	MDR 50	MNH-636
76	61	6.3	MDR 65	MNH-636



Øa	Øi	h	Obj.č.	Obj.č.
36	24.5	6	MDR 25	MNH-628
43.5	28.5	6	MDR-X25	MNH-630
53.5	36.5	6	MDR 35	MNH-628
67	51	6	MDR 50	MNH-636
67	51	6	MDR 50	MNH-636

Øa	Øi	h	Obj.č.	Obj.č.
36	24.5	6	MDR 25	MNH-628
43.5	28.5	6	MDR-X25	MNH-630
53.5	36.5	6	MDR 35	MNH-628
53.5	36.5	6	MDR 35	MNH-628
53.5	36.5	6	MDR 35	MNH-628
55	41	6.5	MDR 42	MNH-628
67	51	6	MDR 50	MNH-636
76	61	6.3	MDR 65	MNH-636

Øa	Øi	h	Obj.č.	Obj.č.
36	24.5	6	MDR 25	MNH-628
43.5	28.5	6	MDR-X25	MNH-630
53.5	36.5	6	MDR 35	MNH-628
55	41	6.5	MDR 42	MNH-628
67	51	6	MDR 50	MNH-636
67	51	6	MDR 50	MNH-636

Øa	Øi	h	Obj.č.	Obj.č.
43.5	28.5	6	MDR-X25	MNH-630
53.5	36.5	6	MDR 35	MNH-628
55	41	6.5	MDR 42	MNH-628
67	51	6	MDR 50	MNH-636
67	51	6	MDR 50	MNH-636